

SEKONIC

EXPOSURE METER

FLASHMATE

L-308B

使用説明書



Operating Instructions

L-308B
FLASHMATE
EXPOSURE METER
SEKONIC



保証書付

お買い上げありがとうございます。ご使用前にこの説明書を必ずお読みいただきこのL-308Bの性能を十分ご活用ください。この説明書は保証書を兼ねていますので、大切に保管してください。

1. 各部の名称



目次

1. 各部の名称	2
2. 液晶表示	3
3. モード選定一覧	4
4. 測定の準備	5
(1) 電池をいれます	5
(2) 測定モードのセット	5
(3) フィルム感度(ISO)のセット	6
(4) シャッター速度(T)のセット	6
5. 定常光の測定	7
6. フラッシュ光・コードレス測定	8
7. フラッシュ光・コード接続測定	9
8. 取扱い上のご注意	10
9. 仕様	11
10. アフターサービスについて	12

2. 液晶表示

モード切り替えキーの操作により

- 1) **flash** コードレス測定
 - 2) **REC** コード接続測定
 - 3) **EV** 定常光測定
- が表示されます。また、定常光測定モードでは **EV** または **F** が表示されます。


- 1) アップ・ダウンキーの操作により タイムが表示されます。

- **T** が表示されているときは シャッター速度が表示されます。

- **S** は秒

- **f/s** はシネコマ数
(**f/s** は定常光測定モードのみ表示)

- 2) ISOキーの操作により **ISO** が表示され、設定フィルム感度が表示されます。



- 1) 電源キーをONしたとき b, c の文字が表示されます。

- 2) 測定F値の整数項が表示されます。


- 3) 測定EV値の整数項が表示されます。

- 4) 測定及び表示範囲外のとき E.u (アンダー)、E.o (オーバー) が表示されます。

- 1) 電源キーをONにしたときに電池容量の表示がされます。
(充满 ~ 空)

- 2) 測定F値、EV値の小数項が表示されます。
(-0.1 ~ +0.9)

3. モード選定一覧



入射光式と反射光式の測定切り換え方法

光球はスライドさせ a、b それぞれのクリック位置で止めて下さい。（図-1）（図-2）

*光球の移動はローレット部を指で押させて動かしてください。（図-3）



図-1 入射光式



図-2 反射光式



図-3

入射光式測定方法

被写体位置で光球をカメラのレンズに向けて測定します。
(図-4)



図-4

反射光式測定方法

- ・カメラ位置、またはカメラ方向から被写体の測定したい部分に露出計のレンズを正しく向けて測定します。（図-5）
 - ・カメラ位置で測定すると被写体全体の平均測定になります。
 - ・部分測定するときは、できるだけ被写体の主要部に近づいて測定してください。
- *露出計等の影が測定部分に入らないように注意してください。



図-5

(1) 電池をいれます。

単3乾電池（L R-6 またはR-6）1.5V1本を使用します。

1. 電池ふたを矢印の方向にひいてはします。（図-6）
2. 電池の十一を電池ケース内の表示に合わせて一側を先に入れ一側に指で押すようにして挿入します。
3. 電池ふたを本体に合わせスライドして閉めます。
確実にかみ合ったことを確認してください。
4. 電源キーを押してONすると液晶表示部にb、c 文字と電池容量を表すドットが表示され（図-7）、その後、測定モードに切り換わります。




図-6

*電池容量が不足すると液晶表示部のb、c 文字が点滅、または表示がされません。

*ONの状態で放置しますとオートOFF機能が働き約4分後に自動的に表示ができます。

*オートOFF後、再使用するときは、電源キーをONしてください。

*設定されたモード及び設定値は、電源OFF又はオートOFF後もメモリーされています。


*Ni-cd蓄電池、リチウム電池は使用できません。



図-7

(2) 測定モードのセット

1. モード切り替えキーを押すことによりロータリー式にモードが変わります。



測定の準備



図-8



図-9

*定常光モードでISOキーを押したままモード切り替えキーを押すとEV値表示とF値表示の切り換えができます。（図-8、図-9）

(3) フィルム感度（ISO）のセット

1. ISOキーを押したままアップ・ダウンドラッグキーでフィルム感度をあわせます。（図-10）

*ISOキーを押したままアップ・ダウンドラッグキーを1秒以上押し続けると、ISO数値が連続して変わります。

(4) シャッター速度（T）のセット

1. アップ・ダウンドラッグキーで設定したいシャッター速度にあわせます。（図-11）



図-10



図-11

2. シネコマ数は1／8000の次に表示されます。（定常光測定のとき）
(図-12)



図-12

3. フラッシュ光測定では1／500の次に1／75、1／80、1／90、1／100のシャッター速度が表示されます。（図-13）



図-13

5. 定常光の測定（EV値、F値）

1. モード切り替えキーを押して、**■**定常光測定モードに切り換えてください。
2. フィルム感度とシャッター速度をセットしてください。
3. 测光スイッチを押すと測定値が表示されます。

*定常光モードでは測光スイッチがON状態では連続測光しています。

*測定後、ISOおよびT（タイム）の変換により測定値の演算が自動的に行われます。

*EV値⇒F値の切換え

ISOキーを押したままモード切り替えスイッチを押すとEV値⇒F値の表示が交互に変わります。（図-14、図-15）

*液晶表示部のドットはF値間を1／10分割した値です。例えば、図-15はF2.0+3／10絞りを表わしています。




図-14



図-15

*測定範囲を外れた場合は、E.u（アンダーエラー）、E.o（オーバーエラー）が表示されます。



6. フラッシュ光・コードレス測定

シンクロコードを使用しないで測定する場合

- モード切り替えキーを押して **■** コードレス測定モードに切り換えてください。
- フィルム感度とシャッター速度をセットしてください。
- 測光スイッチを押すと、**■** マークが点滅し測定待機状態になります。
- フラッシュ光を受光すると F 値が表示されます。（図-16）

*一度測定した後も **■** マークは点滅をつづけ待機状態にあり、再度フラッシュ光を受光すれば F 値は更新されます。

* **■** マークの点滅は約 9.0 秒間継続されます。

* **■** マークが点滅していないと測定はできません。

*コードレスでフラッシュを発光させても露出計が光を感知しないときは、「コード接続測定」にしてください。（周囲光に比べてフラッシュ光がはるかに小さい場合は感知しないことがあります。）

*測定後にシャッター速度を変換すると測定値は消え、F 値は 0 になります。

*ラビット型蛍光灯や特殊な照明下では、フラッシュを発光しないのに動作することがあります。このようなときは、コード接続測定モードにしてシンクロコードを接続し、測定してください。

*測定範囲を外れた場合は、E.u（アンダーエラー）、E.o（オーバーエラー）が表示されます。




図-16



7. フラッシュ光・コード接続測定

シンクロコードを使用して測定する場合

- 本体表面のモード切り替えキーを押して、**■** コード接続モードに切り換えてください。
- フィルム感度とシャッター速度をセットしてください。（図-17）




図-17

3. フラッシュと露出計のシンクロターミナルとをシンクロコードで接続してください。（図-18）

4. 测光スイッチを押すとフラッシュが発光し F 値が表示されます。（図-19）

5. 度測定するときは、そのまま測光スイッチを押してください。新しい F 値が表示されます。

*フラッシュバルブを発光させて測定するときは同調範囲を確認してシャッター速度を設定してください。

*シンクロターミナルにシンクロコードを接続するとき、また電源キーを ON-OFF するときにフラッシュによっては発光するときがあります。

*シャッター速度を設定するときはカメラの同調範囲をあらかじめ確認してください。測定後にタイマ変換すると F 値は 0 になります。

*フラッシュによっては発光しないことがあります。この場合は「コードレス測定」をしてください。

*シンクロコード（**■** コード接続測定のとき）別売
長さ 5 m のコードは 3 つのプラグを持ち、露出計とフラッシュ、カメラとフラッシュを同調させることができるので、撮影をするときにもコードを差し換える必要がなく、大変便利です。また露出計側の接続端子はロック機構がついているので確実に接続することができます。（図-20）





図-19



フラッシュ カメラ
図-20

8. 取扱い上のご注意

お買い上げいただいたSEKONIC FLASHMATE L-308Bは多くの電子部品で構成された精密電子機器ですので、下記の点にご注意ください。

1. 落下または衝撃は絶対にさけてください。
2. 高温、多湿な場所には保管しないでください。
3. 光球、レンズ面にはホコリ・ゴミ・傷がつかないようにしてください。
また、常に、清潔に保つようにしてください。
4. 本体が汚れたときは、乾いた柔らかい布やシリコンクロスでふいてください。
シンナー、ベンジンなどの溶剤は絶対に使用しないでください。
5. 余分な電池の消耗を避けるため、使用時以外は、できるだけ電源をOFFしてください。
6. 正常な動作をしない場合は、電池を取りだし約10秒以上経過してから入れ直してください。
7. 長い間、使用しないときは電池を抜いておいてください。

万一、故障がおきたときは、最寄りの営業所またはサービスセンターにお持ちください。お近くに、営業所またはサービスセンターがなく輸送される場合には厚さ3cm以上の衝撃よけパッキングに包んでから、ダンボールなどで梱包してください。



9. 仕様

測定・測定方式

測定範囲 (ISO 100)

- 入射光式、反射光式兼用
- 定常光、フラッシュ光用デジタル露出計
- 定常光、EV 0 ~ 19 $\frac{1}{10}$ (19.9)
- フラッシュ光 F 1.4 ~ 90 $\frac{1}{10}$ (F 90 + 0.9 紋り)

くり返し精度

受光部

- ±0.1EV以内
- 入射光・・・光球

受光素子

校正定数

表示範囲

- 反射光・・・レンズ (受光角40°)
- シリコンフォトダイオード
- C = 340 K = 12.5
- ISO (フィルム感度) 3 ~ 80000 (1/3S V単位)

- T (シャッター速度) 定常光・・・60秒~1/8000秒 (1TV単位)
f/S (シネコマ数) ・・・8、12、16、1
8、24、25、30、32、64、128
(開角度180°)
- フラッシュ光・・・1秒~1/500秒 (1TV
単位) 他に1/75、1/80、1/90、
1/100

- F (紋り) 0.5 ~ 90 $\frac{1}{10}$
- EV (露出値) -5 ~ 26 $\frac{1}{10}$
- F、EVの小数項 ・・・(0.1) ~ $\frac{1}{10}$ (0.9)

その他の表示

- 測定範囲 E.u (アンダー) E.o (オーバー)

- 測定モード F EV

- バッテリーチェック、b.c $\frac{1}{10}$ ~ $\frac{1}{10}$

使用電池

使用温度範囲

保存温度範囲

標準付属品

大きさ・重さ

- 単3乾電池 (R-6、LR-6) 1.5V 1本

- 0°C ~ 40°C

- 20°C ~ 60°C

- ストラップ、ソフトケース、乾電池1本

- 110 x 63 x 22mm

- 約80g (電池を除く)

*この仕様および外観は改良のため予告なく変更する場合があります。

10 アフターサービスについて

*弊社の製品には一定の期間内無料修理をお引受けする保証書があります。記載事項をお確かめのうえ、大切に保管してください。

●無料保証期間などについて

1. 無料保証期間はお買上げ日より1ヶ年間でございます。
2. 保証書にお買上げ日および販売店名のないものは保証の対象なりませんので、必ずお確かめください。
3. 無料保証期間内でも有料修理となる場合もございますので、保証書の記載事項をお確かめください。
4. 保証期間経過後の修理は有料となります。また、運賃諸掛りはお客様にご負担願います。

●補修用性能部品の保有期間などについて

1. 補修用性能部品は、5年間を目安に保有しております。したがって、本期間中は原則として修理をお受けいたします。なお故障箇所によりましては期間が過ぎても修理可能の場合もありますのでサービスセンターにお問合わせください。
2. 修理可能期間はご使用の状態や環境、お手入れの状態によって異なる場合がありますので、現品をご持参のうえお買上げ店またはサービスセンターにご相談ください。
3. 修理可能期間内でも浸冠水、強度のショック、その他損傷のいじるしいもので、修理後の機能維持に問題が残ると思われますものにつきましては修理不可能となる場合があります。

●修理ご依頼時における留意事項

1. 修理品につきましては、故障内容を、またご指定の修理箇所があります場合には、その指定箇所をできるだけ具体的にお申し出ください。ご指定のない場合には、各部点検をはじめ品質的・性能的に必要と認められるすべてのところを検査・調整・修理することになります。修理料金が加算される場合がありますのでご留意ください。
2. 修理をご依頼されたものの中には、単に電池を交換するだけで正常に作動する「故障していないもの」が見受けられます。電池の容量低下、(十) (一) の逆、定格違いなどについて、よくお確かめください。

●転居の場合の手続きについて

1. 転居で販売店にご依頼しにくい場合は、最寄りのサービスセンターにご相談ください。

●お問合わせ先について

本製品の保証、修理、使い方などのお問合わせは、最寄りのサービスセンターをご利用ください。

本製品の故障が原因で生じたフィルムの損失、様々な出費、迷惑ないし不都合、精神的な損害、その他すべては、補償致しません。

[保証規定]

つきのような場合には保証期間内でも保証の対象とはなりません。

1. 誤ったご使用またはお取扱い上の不注意により生じた故障、または損傷など
2. 保管上の不備によるもの、およびご使用者の責に帰すと認められる故障、または損傷など
3. 弊社の指定する修理取扱い所以外で行われた修理・改修・分解掃除などによる故障、または損傷
4. 火災、地震、水害、公害、指定外の使用電池（電圧）およびその他の天災地変や落下、衝撃などによる故障または損傷
5. 保証書のご提示がない場合
6. 保証書にお買上げ日、保証期間、販売店名などの記載の不備な場合あるいは字句を書き換えられた場合
7. ご使用後の内・外装面のキズ、部品や付属品の紛失による修復交換、電池などの消耗品類の品切れや交換
8. 各部点検、精密検査、分解掃除等を特別にご依頼された場合
9. 本製品の故障に起因する付隨的損害（撮影に要した諸費用および撮影により得べかりし利益の喪失など）については保証いたしかねます。
10. お買上げ店または弊社サービスセンターにご持参いただく際に際しての諸費用は、お客様にご負担願います。またお買上げ店と弊社間の運賃諸掛りにつきましては、輸送方法などによって、（問屋便以外を使用した場合）一部ご負担いただく場合があります。

*ご注意

1. 本保証書は、以上の保証規定により無料修理をお約束するもので、これによりお客様の法律上の権利を制限するものではありません。
2. 本保証書の表示について、ご不明の点は弊社サービスセンターにお問い合わせください。
3. 保証書をお受取りの際は、販売店名および購入年月日などが記入されているかどうかをご確認ください。万一記入もれがありました場合には、ただちにお買上げ店へお申し出ください。
4. 保証書の再発行はいたしませんので大切に保存してください。
5. 本保証書は日本国内においてのみ有効です。

[アフターサービスについて]

1. 部品の保有期間など。アフターサービスに関する事項につきましては取扱説明書に詳しく記載しておりますので、ぜひご覧ください。
2. 修理完了品には、弊社の修理納品書が発行されますのでお確かめください。
3. 保証期間経過後の修理などについてのお問合わせは弊社サービスセンターをご利用ください。



ユーザー メモ

保証書

このたびは、セコニック露出計をお買上げいただきまして有難く厚く御礼申し上げます。

この製品は弊社が心をこめて皆様にお届け申し上げたものでございますが、使用説明書にもとづく通常のご使用状態において、万一保証期間内に故障が生じました場合には、本保証書を現品に添えてお買上げの販売店または最寄りの弊社サービスセンターにご持参くだされば、保証期間内に限り無料にて修理・調整させていただきます。

露出計機種 L-308B N o.

お買上げ日	年	月	日
保証期間 (お買上げ日より1ヶ年間です)	年	月	日



〒178 東京都練馬区大泉学園町7-24-14 TEL 03 (3978) 2330

ご住所

ご氏名

露出計営業：〒162 東京都新宿区市ヶ谷田町3-8 新杵ビル
TEL 03-3269-7245 FAX 03-3269-0580

大阪営業所：〒541 大阪市中央区本町 2-3-6 本町ビジネスビル
TEL 06-263-1571 FAX 06-261-2072

名古屋営業所：〒460 名古屋市中区栄 5-8-14 万国ビル
TEL 052-251-6201 FAX 052-251-6227

東京サービスセンター：〒162 東京都新宿区市ヶ谷田町 3-8 新杵ビル
TEL 03-3269-7243 FAX 03-3269-0580

キリトリ

販売店名

1. Parts Designations




Table of Contents


1. Parts Designations	E-1
2. Liquid Crystal Display	E-2
3. Mode Selection	E-3
4. Preparation for Measurement	E-4
(1) Inserting the battery	E-4
(2) Setting the measurement mode	E-4
(3) Setting the film speed (ISO)	E-5
(4) Setting the shutter speed (T)	E-6
5. Ambient Light Measurement	E-6
6. Flash Light Wireless Measurement	E-7
7. Flash Light Wired Measurement	E-8
8. Precautions on Handling	E-9
9. Specifications	E-10



2. Liquid Crystal Display

By operating the mode selection switch,
(1) **f** (wireless measurement)
(2) **f** (wired measurement), or
(3) **l** (ambient light measurement)
is displayed. In the ambient light
measurement mode, **EV** or **F** is
displayed.

- (1) By operating the UP/DOWN button, the time is displayed.
 - When **T** mark is shown, shutter speed is indicated.
 - **S** represents second.
 - **f/s** represents the cine scale (displayed only in the ambient light measurement mode). **ISO**
- (2) By operating the ISO and Up/Down buttons the film speed can be set.




- (1) When the power is turned ON, "b.c" is displayed.
- (2) The integer of the F value measured is displayed.
- (3) The integer of the EV value measured is displayed.
- (4) When the measurable or display range is exceeded, E.u (underexposure) or E.o (overexposure) is displayed. As mentioned in specification.

- (1) When the power is turned ON, the remaining battery capacity is displayed.

(**■■■** ~ **■■■**)
- (2) Fractions of the F or EV value measured are displayed.

(**■■■** (0.1) ~ **■■■** (0.9))

3. Mode Selection



Switching between the incident or reflected light method of measurement

Slide the lumisphere to the a or b click position. (Figs. 1 and 2).

★ Hold down and move the knurled part to move the lumisphere (Fig. 3).



Fig. 1 Incident Light Method




Fig. 2 Reflected Light Method



Fig. 3



Fig. 4



Fig. 5

Incident Light Method Measurement

Place the exposure meter at the position of the subject to be photographed with the lumisphere facing the camera lens for measurement (Fig. 4).

Reflected Light Method Measurement

- Place the exposure meter at the position of the camera or in the same direction as the camera with the lens facing the desired part of the subject to be photographed for measurement (Fig. 5).
- If the exposure meter is placed at the position of the camera for measurement, the average value for the overall subject is obtained.
- For partial measurement, place the exposure meter as close as possible to the desired part of the subject.
- ★ Be careful not to allow the exposure meter shadow or other object to affect the measured part.

4. Preparation for Measurement

(1) Inserting the battery

Use a 1.5-V "AA" battery (UM3 dry, LR-6 or R-6).

1. Slide the battery case cover in the direction of the arrow to remove it (Fig. 6).
2. Insert the battery into the battery case, observing the (+) and (-) indications on the inner surface of the case. Insert the (-) end first, then push the battery in toward the (-) side.
3. Slide the battery case cover along the unit to close it. Check that the cover is securely closed.
4. Press the power switch to turn ON the power. "b c" and bar symbols indicating the battery capacity appear on the liquid crystal display (Fig. 7), then the meter is switched to the measurement mode.




Fig. 6



Fig. 7

- ★ When the remaining battery capacity is low, the "b c" display flashes or disappears.
- ★ If the meter is left ON, the auto-off function is activated, automatically switching off the display in about four minutes.
- ★ To use the meter again after auto-off, turn ON the power.
- ★ The mode setting is held even after power OFF or auto-off.
- ★ Ni-cd or lithium batteries cannot be used.

(2) Setting the measurement mode

1. Every time the mode selection button is pressed, functions (mode) cycle as follows:



Preparation for Measurement



Fig. 8



Fig. 9

★ You can switch the EV or F value display by pressing the mode selection button while holding down the ISO button in the ambient light measurement mode (Figs. 8 and 9).

(3) Setting the film speed (ISO)

1. Press either side of the UP/DOWN button while holding down the ISO button to set the film speed (Fig. 10).

★ The ISO value is continuously changed by keeping either side of the UP/DOWN button held down for more than 1 second while holding down the ISO button.

(4) Setting the shutter speed (T)

1. Press either side of the UP/DOWN key to set the shutter speed (Fig. 11).



Fig. 10




Fig. 11

2. After "1/8000" appears, the cine scale is displayed. The cine scale is based on a 180° shutter blade opening. (Fig. 12)




Fig. 12

3. In the flash light measurement mode, the shutter speed of "1/75", "1/80", "1/90" then "1/100" are displayed after "1/500" (Fig. 13).



Fig. 13

5. Ambient Light Measurement (EV or F value)

1. Press the selection key to set the ambient light measurement mode.
2. Set the film and shutter speeds.
3. Press the measuring switch to display the measured value.




Fig. 14


- ★ In the ambient light measurement mode, light measurement is continuously conducted while the measuring switch is set to ON.
- ★ After measurement, measured values are automatically calculated by changing the ISO or T (time) setting.
- ★ Switching between EV and F value display. Press the mode selection switch while holding down the ISO key. The above 2 illustrations refer to switching between EV or F value. (Figs. 14 and 15).
- ★ Each bar symbol on the liquid crystal display expresses 1/10 of the F value. For example, Fig. 15 expresses F2.0 + 3/10 stop.
- ★ If the measuring range is exceeded, the digital F-stop number is replaced with either mark of E.u. (underexposure) or E.o.(overexposure).



Fig. 15



E.u



E.o

6. Flash Light Wireless Measurement

Measurement without using the synchro cord

1. Press the mode selection key to set the **flash** wireless measurement mode.
2. Set the film and shutter speeds.
3. When the measuring switch is pressed, the **flash** mark starts flashing, indicating the waiting state.
4. When the meter receives a flash burst, the F value is displayed (Fig. 16).

- ★ Even after light measurement, the **flash** mark continues flashing, indicating the waiting state. When the meter receives another flash, the previous F value is replaced by the new F value.
- ★ The **flash** mark continues flashing for about 90 seconds.
- ★ Light cannot be measured unless the **flash** mark is flashing.
- ★ If the meter does not detect a light in the wireless measurement mode even if a flash occurs, switch to the wired measurement mode. (The meter may not sense when flash light is less bright than surrounding light.)
- ★ If the shutter speed setting (T) is changed after measurement, the measured value is erased and the F value displayed as "0".
- ★ If the measuring range is exceeded, the digital F-stop number is replaced with either mark of E.u. (underexposure) or E.o.(overexposure).



Fig. 16



7. Flash Light Wired Measurement

Measurement using the synchro cord

1. Press the mode selection key to set the **flash** wired measurement mode (Fig. 17).
 2. Set the film and shutter speeds.
 3. Connect a flash unit to the synchro terminal of the meter using the synchro cord (Fig. 18).
 4. Press the measuring switch to produce a flash and display the F value (Fig. 19).
 5. To measure another flash, press the measuring switch again and a new F value is displayed.
- ★ Set the shutter speed after checking the synchronization range of the flashbulb.
 - ★ Connecting the synchro cord to the synchro terminal or switching ON/OFF causes some flash units to fire.
 - ★ Before setting the shutter speed, check and confirm the synchronization range of the camera. When time conversion is made after measurement, the F value become "0".
 - ★ If the flash unit does not fire, measure light in the wireless measurement mode.



Fig. 17



Fig. 18



Fig. 19



Fig. 20

8. Precautions on Handling

Since the Sekonic Flashmate L-308B is a precision electronic instrument consisting of many electronic parts, observe the following points:

1. Never drop it or apply impact to it.
2. Do not keep in a high-temperature or humid place.
3. Keep the lumisphere and lens surfaces clean and free from dust, foreign particles and scratches.
4. Wipe off dirt with a soft or silicon cloth. Never use solvent such as thinner or benzine.
5. To prevent battery wastage, keep the power OFF as much as possible when not in use.
6. If the meter does not operate normally, remove the battery, wait for about 10 seconds, then re-insert the battery.
7. Remove the battery if the meter is not to be used for a long time.

In the case of failure, take the meter to the nearest dealer or send it to the service center. If mailing the meter, wrap it in 3-cm or thicker shock-absorbing material, then pack it in a corrugated cardboard box.

9. Specifications

Measurement	<ul style="list-style-type: none">• Incident and reflected light methods• Digital exposure meter for ambient and flash lights
Measuring range (ISO100)	<ul style="list-style-type: none">• Ambient light: EV0 to 19 $\frac{1}{10}$ sec. (19.9)• Flash light: F1.4 to 90 $\frac{1}{10}$ sec. (F90 + 0.9 stop)• ± 0.1 EV or less
Repeat accuracy	<ul style="list-style-type: none">• Incident light: Lumisphere• Reflected light: Lens (light receiving angle of 40°)
Light receiving section	<ul style="list-style-type: none">• Silicon photo diode
Light receiving element	<ul style="list-style-type: none">• C = 340, K = 12.5
Calibration constant	<ul style="list-style-type: none">• ISO (film speed): 3 to 8,000 (unit: 1/3 SV)
Display range	<ul style="list-style-type: none">• T (shutter speed) : Ambient light: 60 sec to 1/8,000 sec. (unit: 1 TV)• f/s (cine scale) : 8, 12, 16, 18, 24, 25, 30, 32, 64 or 128
Other display	<ul style="list-style-type: none">• Opening angle : 180°• Flash light : 1 sec to 1/500 sec. (unit: 1 TV) plus 1/75, 1/80, 1/90 or 1/100 sec.• F (stop): 0.5 to 90 $\frac{1}{10}$ sec.• EV (exposure value): -5 to 26 $\frac{1}{10}$ sec.• Fractions of F or EV value: $\frac{1}{2}$, $\frac{1}{3}$, $\frac{1}{4}$, $\frac{1}{5}$, $\frac{1}{6}$, $\frac{1}{7}$, $\frac{1}{8}$, $\frac{1}{9}$, $\frac{1}{10}$, $\frac{1}{11}$, $\frac{1}{12}$, $\frac{1}{13}$, $\frac{1}{14}$, $\frac{1}{15}$, $\frac{1}{16}$, $\frac{1}{17}$, $\frac{1}{18}$, $\frac{1}{19}$, $\frac{1}{20}$, $\frac{1}{21}$, $\frac{1}{22}$, $\frac{1}{23}$, $\frac{1}{24}$, $\frac{1}{25}$, $\frac{1}{26}$, $\frac{1}{27}$, $\frac{1}{28}$, $\frac{1}{29}$, $\frac{1}{30}$, $\frac{1}{31}$, $\frac{1}{32}$, $\frac{1}{33}$, $\frac{1}{34}$, $\frac{1}{35}$, $\frac{1}{36}$, $\frac{1}{37}$, $\frac{1}{38}$, $\frac{1}{39}$, $\frac{1}{40}$, $\frac{1}{41}$, $\frac{1}{42}$, $\frac{1}{43}$, $\frac{1}{44}$, $\frac{1}{45}$, $\frac{1}{46}$, $\frac{1}{47}$, $\frac{1}{48}$, $\frac{1}{49}$, $\frac{1}{50}$, $\frac{1}{51}$, $\frac{1}{52}$, $\frac{1}{53}$, $\frac{1}{54}$, $\frac{1}{55}$, $\frac{1}{56}$, $\frac{1}{57}$, $\frac{1}{58}$, $\frac{1}{59}$, $\frac{1}{60}$, $\frac{1}{61}$, $\frac{1}{62}$, $\frac{1}{63}$, $\frac{1}{64}$, $\frac{1}{65}$, $\frac{1}{66}$, $\frac{1}{67}$, $\frac{1}{68}$, $\frac{1}{69}$, $\frac{1}{70}$, $\frac{1}{71}$, $\frac{1}{72}$, $\frac{1}{73}$, $\frac{1}{74}$, $\frac{1}{75}$, $\frac{1}{76}$, $\frac{1}{77}$, $\frac{1}{78}$, $\frac{1}{79}$, $\frac{1}{80}$, $\frac{1}{81}$, $\frac{1}{82}$, $\frac{1}{83}$, $\frac{1}{84}$, $\frac{1}{85}$, $\frac{1}{86}$, $\frac{1}{87}$, $\frac{1}{88}$, $\frac{1}{89}$, $\frac{1}{90}$, $\frac{1}{91}$, $\frac{1}{92}$, $\frac{1}{93}$, $\frac{1}{94}$, $\frac{1}{95}$, $\frac{1}{96}$, $\frac{1}{97}$, $\frac{1}{98}$, $\frac{1}{99}$, $\frac{1}{100}$• Measuring range E.u (underexposure) and E.o (overexposure)• Measurement mode and • Battery check: b.c $\frac{1}{10}$ sec. to $\frac{1}{10}$ sec.• One "AA" battery (UM3 dry R-6, LR-6), 1.5 V• 0°C to 40°C• -20°C to 60°C• Strap, soft case and dry battery (one)• 110 × 63 × 22 mm• Approx. 80 g (excluding the battery)
Battery used	
Operating temperature range	
Storage temperature range	
Standard accessories	
Size and weight	

★ The specifications and appearance are subject to change without notice due to

SEKONIC CO., LTD.

7-24-14, Oizumi-Gakuen-cho, Nerima-ku, Tokyo 178, Japan
Phone: Tokyo (03) 3978-2335 Telex: J 34376 SEKONIC
Facsimile: (03) 3978-5229 Cable: SEKONIC TOKYO

ユーザーメモ

ユーザーメモ